

TABLE OF CONTENTS

EXECUTIVE SUMMARY	1
1.0 INTRODUCTION.....	1
1.1 Scope of Services	1
1.2 Limitations, Deviations, and Limiting Conditions	2
1.3 Terms, Conditions and User Reliance	2
2.0 RECORDS REVIEW.....	2
2.1 Physical Setting.....	3
2.2 Environmental Database Search.....	3
2.2.1 Methodology	4
2.2.2 Results.....	4
2.3 Owner Provided Documents	5
2.4 State/Federal Regulatory Agency Documents	5
2.5 Local File Review	5
2.6 Historical Use Information.....	6
2.7 User Provided Information	7
3.0 SITE RECONNAISSANCE.....	7
4.0 INTERVIEWS.....	9
4.1 Interview with Site Owner/Key Site Manager.....	9
4.2 Interviews with Local Government Officials.....	9
5.0 EVALUATION	9
5.1 Findings, Opinion, and Conclusions.....	9
5.2 Data Gaps	9
5.3 References	10
5.4 Signatures of Environmental Professionals	10
6.0 QUALIFICATIONS OF ENVIRONMENTAL PROFESSIONALS.....	10

TABLE

Table 1 Summary of DEP File Review Information

FIGURES

Figure 1 Locus Plan
 Figure 2 Site Plan
 Figure 3 Site Vicinity Plan

TOWN CLERK, ROCKLAND
 FEB 8 '22 PM3:36